

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35SWNW

Location ID: 335001

Date: 1/14/2025



Location – Photo #05945



Location – Photo #05942

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35SWNW

Location ID: 335001

Date: 1/14/2025



Location – Photo #05931



Location – Photo #05944

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35SWNW

Location ID: 335001

Date: 1/14/2025



Location – Photo #05941



Location – Photo #05943

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35SWNW

Location ID: 335001

Date: 1/14/2025



Illegible Tank Label – Photo #05934

Stained Soil in Containment Area – Photo #05935

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CIRCLE B LAND-66S92W/35SWNW

Location ID: 335001

Date: 1/14/2025



Stored Supplies – Photo #05949



Unused Equipment – Photo #05946