

**COLORADO OIL & GAS COMMISSION
FIELD INSPECTION**

COMMISSION

 15 1996
 C

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 017 - 7202		LEASE NAME: MPU 13G-30	
LOCATION: NWSW 30-135-47W		OPERATOR: UPRC	
DATE: 4-15-96		INSPECTOR: P. VanSickle	
Insp. Type: ID	Insp. Status: TA	PA: Y N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	✓	
Pits (Reserve/Production) (Rule 902, 903, 904)	None. SCANNED	
Fences (Rule 604.C.(3), 1003.A)	N/A	
Tank Battery Equipment (Rule 604)	None. ✓	
Fire Walls/Berms/Dikes (Rule 604)	N/A.	
General Housekeeping (Rule 603.G)	OK	
Spills (Oil/Water) (Rule 908)	None.	
Bradenhead (Rule 207)	—	
Drilling Well/Workover (Rule 315)	—	
Surface Rehabilitation (Rule 317)	—	
Miscellaneous	Location in wellmasters is NWWW, well is in NWSW.	

CORRECTIVE ACTION REQUIRED: None.

Date Corrective Action Required By:
Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site