

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location Overview – Photo #05979



Location – Photo #05983

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location – Photo #05992



Location – Photo #05980

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location – Photo #05993



Location – Photo #05994

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location – Photo #05990



Location – Photo #05981

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location – Photo #05982



Location – Photo #05996

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Location – Photo #05981



Location – Photo #05998

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Unused Equipment – Photo #05985



Unused Equipment/Wildlife Entry Hazard – Photo #05986



Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Unused Equipment/Wildlife Entry Hazard – Photo #05988



Unused Equipment/Wildlife Entry Hazard – Photo #05989

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW

Location ID: 335200

Date: 1/15/2025



Open-Ended Line Near Gas Meters – Photo #05995



Corrosion on Storage Tank – Photo #05991