

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025




Photo # 2492 Entrance to location




Photo # 2510 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2495 Location



Photo # 2499 Location



Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2508 Location



Photo # 2517 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2519 SW corner of location



Photo # 2520 NW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2521 NE corner of location



Photo # 2507 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2523 Wildlife hazard/Personnel safety hazard

Photo # 2525 Wildlife hazard/Personnel safety hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza Ranch/2 Pad

Location ID: 312689

Date: 01/13/2025



Photo # 2514 inaccurate capacity