

Final Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 409555

Well Name: HSR-AMATO #4-1

Inspection Document #: 718600172

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-AMATO #4-1
Location ID: 409555



Photo 1. Picture taken looking west from former well site (API #123-20382). Desirable perennial vegetation has established on site. List B noxious weed Scotch thistle is present on location.

Inspection Photos
Location Name: HSR-AMATO #4-1
Location ID: 409555



Photo 2. Photo looking north from well site. See Photo 1 comments.



Photo 3. Photo looking south from well site. See Photo 1 comments.

