

Inspection Photos
Location Name: Barber 44-8 5N46W
API Number: 125-09393



1. Lease sign at well location.




2. View of wellhead.

Inspection Photos
Location Name: Barber 44-8 5N46W
API Number: 125-09393



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Barber 44-8 5N46W
API Number: 125-09393



5. Gas meter inside meter shed.



6. Gathering location overview.