

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0620-33 Pad

Location ID: 335204

Date: 01/14/2025



Photo # 2737 Entrance to location




Photo # 2759 Location

Inspection Photos
Location: LARAMIE ENERGY LLC CC/0620-33 Pad
Location ID: 335204
Date: 01/14/2025



Photo # 2738 Location



Photo # 2751 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0620-33 Pad

Location ID: 335204

Date: 01/14/2025



Photo # 2758 Location



Photo # 2764 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0620-33 Pad

Location ID: 335204

Date: 01/14/2025



Photo # 2765 SE corner of location




Photo # 2745 Bradenhead line tied into flowline/no FORM 4 SUNDRY/not in compliance with CECMC rules

Inspection Photos
Location: LARAMIE ENERGY LLC CC/0620-33 Pad
Location ID: 335204
Date: 01/14/2025



**Photo # 2746 Bradenhead line tied into flowline/no FORM 4
SUNDRY/not in compliance with CECMC rules**



**Photo # 2748 Bradenhead line tied into flowline/no FORM 4
SUNDRY/not in compliance with CECMC rules**