

Inspection Photos
Location Name: UPRR 24 PAN AM C 2
Location ID: 319935



Pic 1 tanks



Pic 2 trash on location needs to be removed

Inspection Photos
Location Name: UPRR 24 PAN AM C 2
Location ID: 319935



Pic 3 GMR, Separator



Pic 4 Unable to access wellhead due to road being plowed.