

Inspection Photos
Location Name: Bruchez 3
Location ID: 319736



Pic 1 pump jack



Pic 2 wellhead, tubing and rods need to be removed from location

Inspection Photos
Location Name: Bruchez 3
Location ID: 319736



Pic 3 tubing and rods need to be removed from location



Pic 4 wellhead sign