


Inspection Photos  
Location Name: Korf 4-25  
API Number: 125-08813



1. Lease sign at well location. Note incorrect operator and incorrect emergency contact information.



2. View of wellhead.



Inspection Photos  
Location Name: Korf 4-25  
API Number: 125-08813



3. Well location overview.



4. Lease sign at gathering location. Note incorrect emergency contact information.

**Inspection Photos**  
**Location Name: Korf 4-25**  
**API Number: 125-08813**



**5. Gas meter inside meter shed.**



**6. Gathering location overview.**

