

**Inspection Photos**  
**Location Name: Korf 2**  
**API Number: 125-07076**



**1. Lease sign at well location.**




**2. View of wellhead.**

**Inspection Photos**  
**Location Name: Korf 2**  
**API Number: 125-07076**



**3. Well location overview.**



**4. Lease sign at shared gathering location.**



**Inspection Photos**  
**Location Name: Korf 2**  
**API Number: 125-07076**



**5. Additional view of lease signs at gathering location. Note the Korf 2 lease sign is unreadable.**



**6. Produced water tank at gathering location. No sign or readable labels on tank.**

**Inspection Photos**  
**Location Name: Korf 2**  
**API Number: 125-07076**



**7. Gas meter inside shed.**



**8. Gathering location overview.**