

Inspection Photos
Location Name: Hillman 1
API Number: 125-06396



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Hillman 1
API Number: 125-06396



3. Well location overview.



4. Lease sign at remote gathering location. Note sign is faded and no emergency contact information on sign.

Inspection Photos
Location Name: Hillman 1
API Number: 125-06396



5. Gas meter inside meter shed.



6. Gathering location overview.