

Inspection Photos
Location Name: Clifford Day 24-1
API Number: 125-06875



1. Lease sign at well location. Note incorrect operator on sign and no emergency contact information.




2. View of wellhead and flowline.

Inspection Photos
Location Name: Clifford Day 24-1
API Number: 125-06875



3. Well location overview.



4. Lease sign in shared gathering meter shed.

Inspection Photos
Location Name: Clifford Day 24-1
API Number: 125-06875



5. View of shared meter shed.



6. Calibration log with incorrect well API number.

Inspection Photos
Location Name: Clifford Day 24-1
API Number: 125-06875



7. Flowline mounted separator box.



8. Gathering location overview.

