

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2809 Entrance to location

Photo # 2861 Location

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2810 Location



Photo # 2824 Location

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2825 Location



Photo # 2848 Location

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2860 Location



Photo # 2876 SW corner of location

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2878 NW corner of location



Photo # 2879 NE corner of location

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2881 SE corner of location



Photo # 2834 Wildlife hazard/Personnel safety hazard

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2838 Wildlife hazard/Personnel safety hazard



Photo # 2851 Lacks required information

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2855 Wildlife hazard




Photo # 2856 Wildlife hazard

Inspection Photos

Location: QB ENERGY ORCHARD-68S96W/17SWSW (M17OU)

Location ID: 311752

Date: 01/15/2025



Photo # 2870 Wildlife hazard

