

Inspection Photos
Location Name: QB Energy SOURS 15-11A (L15W) Pad
Location ID: 334643



Photo # 9806 From entrance to location



Photo # 9807 From entrance to location

Inspection Photos

Location Name: QB Energy SOURS 15-11A (L15W) Pad

Location ID: 334643




Photo # 9808 Location



Photo # 9809 Location



Inspection Photos
Location Name: QB Energy SOURS 15-11A (L15W) Pad
Location ID: 334643



Photo # 9810 Location



Photo # 9811 Location

Inspection Photos
Location Name: QB Energy SOURS 15-11A (L15W) Pad
Location ID: 334643



Photo # 9812 Location



Photo # 9813 Location

Inspection Photos
Location Name: QB Energy SOURS 15-11A (L15W) Pad
Location ID: 334643




Photo # 9814 Location



Photo # 9815 Shed inside secondary containment that has a catalytic heater inside

Inspection Photos
Location Name: QB Energy SOURS 15-11A (L15W) Pad
Location ID: 334643



**Photo # 9816 Catalytic heater inside secondary containment
/fire & safety hazard**