

Inspection Photos
Location Name: Tuell, Harry J 1
API Number: 125-06151



1. Lease sign at well location.



2. View of wellhead. Note debris on ground inside shed.

Inspection Photos
Location Name: Tuell, Harry J 1
API Number: 125-06151



3. Separator/Well shed. Door is off shed and on ground at well location.



4. Sign at buried produced water tank.

Inspection Photos
Location Name: Tuell, Harry J 1
API Number: 125-06151



5. Calibration log with incorrect well API number.



6. Old fencing piled on well location.

Inspection Photos
Location Name: Tuell, Harry J 1
API Number: 125-06151



7. Separator/Well shed door.



8. Location overview.