

Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306926

Inspection Document #: 714001721

La Plata County, CO

Township: SWSE 2 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bonifacio Gallegos A3
Location ID: 306926



Photo 1. View of well pad taken from the access point facing center.

1/14/25
156° SE





Photo 3. Produced water tank label has deteriorated and no longer legible.

1/14/25
199° S



Photo 4. Reference area composed of Big Sagebrush, Rubber Rabbitbrush and Broom Snakeweed.

