

# Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333838

Inspection Document #: 714001723

La Plata County, CO

Township: NENW 2 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bradfield CH 1, 3  
Location ID: 333838

1/14/25  
335° NW



Photo 1. View of well pad taken from the access point facing center.









**Photo 3.** Labels at separator are deteriorating, future maintenance is advised.





**Photo 4.** Reference area composed of Juniper, Broom Snakeweed and Sage Brush.