

Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333999

Inspection Document #: 714001726

La Plata County, CO

Township: NWNE 4 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lila Cummins A3, 4
Location ID: 333999



Photo 1. View of well pad from the access point facing center.

Inspection Photos
Location Name: Lila Cummins A3, 4
Location ID: 333999

1/14/25
171° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Interim reclamation composed of Sand Dropseed, Intermediate Wheatgrass, Blue Grama and Rabbitbrush.

API #: 067-09602, 09617

Inspection Photos
Location Name: Lila Cummins A3, 4
Location ID: 333999



Photo 3. Pump jacks/well heads have been cleared of encroaching vegetation.

Inspection Photos
Location Name: Lila Cummins A3, 4
Location ID: 333999

1/14/25
220° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Rutting observed on the active pad, additional stabilization/grading is needed.

API #: 067-09602, 09617

Inspection Photos
Location Name: Lila Cummins A3, 4
Location ID: 333999

1/14/25
272° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Sagebrush, Sand Dropseed and Rabbitbrush.

API #: 067-09602, 09617