

Audit Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



Photo # 745 From entrance to location



Photo # 746 From entrance to location

Audit Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572




Photo # 747 Location



Photo # 748 Location

Audit Photos
Location Name: QB Energy SAVAGE 1-34 (RI1) Pad
Location #: 334572



Photo # 749 Location

Photo # 750 Location

Audit Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



Photo # 751 Location



Photo # 752 Location

Audit Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



Photo # 7207 From audit 708905436 conducted on 01/07/2025 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 753 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife