

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Former separator locations on west end of location

Location Name: Waag North NENW Pad 1 Location ID 439195



ECMC
40.56799, -104.70915, 4852.6ft
01/23/2025 09:28:23



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Waag 4 05-123-40345 Location with flowline risers

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Waag 4 05-123-40345 and Waag 5 05-123-40341 wells and flowline risers

Location Name: Waag North NENW Pad 1 Location ID 439195



ECMC
40.56806, -104.7093, 4852.3ft
01/23/2025 09:28:07



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Waag 3 05-123-40344 location with 1" riser present

Location Name: Waag North NENW Pad 1 Location ID 439195



ECMC
40.5681, -104.70944, 4854.2ft
01/23/2025 09:27:52



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Overview of Waag 1, 2, 3, 4, 5 wells looking east

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Waag 1 05-123-40342 location with flowline risers

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Flowline risers near tank battery, flowline risers require assessment with soil samples for laboratory analysis of Table 915-1 Contaminants of Concern.

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Buried condensate vessel requires assessment with soil samples for laboratory analysis of Table 915-1 Contaminants of Concern.


Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Flowline riser near tank battery, flowline risers require assessment with soil samples for laboratory analysis of Table 915-1 Contaminants of Concern.

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Flowline on east end of pad. Flowline risers require assessment with soil samples for laboratory analysis of Table 915-1 Contaminants of Concern.

Location Name: Waag North NENW Pad 1 Location ID 439195



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Buried condensate vessel requires assessment with soil samples for laboratory analysis of Table 915-1 Contaminants of Concern.