

Inspection Photos

01/17/2025

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677

Inspection Doc: 718100193

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show interim reclamation pursuant to 1003 requirements has not been performed; photos also examples showing trash/debris/vehicles/trailers, and other various items that are not necessary for production being stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 3: Photos 3-4 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Photos also show interim reclamation pursuant to 1003 requirements has not been performed; photos also examples showing trash/debris/vehicles/trailers, and other various items that are not necessary for production being stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 4:



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 5: Photo examples of the soil surface along the unused areas of the Location; gravel/road base material has not been removed, areas have not been decompacted, recontoured/regraded and reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 6: Photo taken from the north end of the Location. Photo shows unused/unneeded pipe stored on the Location. Pipe is open and a potential wildlife entrapment issue.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 7: Photos 7-10 taken from the north and eastern areas of the current pad area. Photos examples showing trash/debris/vehicles/trailers, and other various items that are not necessary for production, being stored on areas of the Location subject to 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 9: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 10: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 11: Photos 11-12 taken from the southwestern areas of the current pad area. Photos examples showing trash/debris/vehicles/trailers, and other various items that are not necessary for production, being stored on areas of the Location subject to 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



January 17, 2025



January 17, 2025

Photo 12: See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 311677



Photo 13: 2023 Google Earth aerial imagery. Red polygons (~2.5 acres) represent approximate areas of the Location not necessary for production subject 1003 to reclamation requirements- reclamation work including, but not limited to, compaction alleviation, recontouring/regrading the cut and fill slopes, and revegetation of areas not necessary for production has not been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources