

## Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad

Location #: 334622



Photo # 9403 From entrance to location



Photo # 9404 From entrance to location

# Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad

Location #: 334622




Photo # 9405 Location

Photo # 9406 Location

## Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad

Location #: 334622



Photo # 9407 Location



Photo # 9408 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad**  
**Location #: 334622**



**Photo # 9409 Location**

**Photo # 9410 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad**  
**Location #: 334622**



**Photo # 9411 Location**

**Photo # 9412 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad**  
**Location #: 334622**



**Photo # 9413 Location**

**Photo # 9414 Location**

## Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad

Location #: 334622



Photo # 9415 Location



Photo # 9416 Open ended load line

**Inspection/Audit Photos**  
**Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad**  
**Location #: 334622**



**Photo # 9417 Enclosure containing piping & catalytic heater inside secondary containment**



**Photo # 9418 Catalytic heater inside secondary containment /fire & safety hazard**

## Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 14-4 (D14) Pad

Location #: 334622



**Photo # 9419 Pipe enclosure available for entry by wildlife  
/wildlife hazard**