

# Inspection Photos

Loc:333961

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/24/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the access road. Erosion occurred along the road side and rock check dams have been displaced.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:333961 | Date: 1/24/2025

## Inspection Photos



**Photo 2.** There is erosion at this culvert outlet and along the fill slope of the location shown at red arrow..



Inspection Photos



**Photo 3.** The pit at the south side of the location was nearing freeboard.



Inspection Photos



**Photo 4.** Facing northwest toward the fill slope. Red arrow points to the culvert outlet shown in photo #2.

