

Inspection Photos

01/17/2025

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623

Inspection Doc: 718100205

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 1: Photos 1-2 taken from the west end of the location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 3: Photos 3-4 taken from the northeast end of the Location. Photos provide an overview of the Location from southeast, south, southwest to west. Photos also show interim areas of the Location; vegetation throughout the interim areas that was visible appears to be predominantly Undesirable, Weedy Plant Species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 5: Photos 5-8 taken from the interim areas on the north end of the Location. Photos examples showing various equipment/vehicles, and other miscellaneous items being stored within the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 7: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 8: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418623



Photo 9: Wildlife protection measures missing from containment BMPs