

Inspection Photos

01/17/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335007

Inspection Doc: 718100205

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335007



Photo 1: Photos 1-2 taken from the north end of the location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335007



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335007



Photo 3: Photos examples showing the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335007



January 17, 2025



January 17, 2025

Photo 4: Label on container is no longer legible.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources