

Inspection Photos

01/17/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 413476

Inspection Doc: 718100211

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413476



Photo 1: Photos 1-2 taken from the north end of the location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413476



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 413476



Photo 3: Fluids from the methanol pumps appears to have spilled into containment. Wildlife protection BMPs missing from containment measures.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources