

Inspection/Audit Photos

Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad

Location #: 334616




Photo # 1669 From entrance to location

Photo # 1670 Location

Inspection/Audit Photos
Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad
Location #: 334616



Photo # 1671 Location

Photo # 1672 Location

Inspection/Audit Photos
Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad
Location #: 334616



Photo # 1673 Location



Photo # 1674 Location

Inspection/Audit Photos

Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad

Location #: 334616



**Photo # 1675 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**