


Trash observed along the length of the lease road.




Excavation at the former wellhead has been backfilled. Trash observed.





Trash observed along the length of the lease road.




Excavation at the former wellhead has been backfilled.





Trash observed along the length of the lease road.



Wildlife tracks observed.

