

Adequate signage installed.






Ruts observed.





Excavations remain open with flowlines and snow accumulation.





Soil stockpiled on location with adequate BMPs.





Soil stockpiled on location with adequate BMPs.



Soil stockpiled on location with inadequate BMPs.





Soil stockpiled on location with adequate BMPs.



Excavation remains open.





Stained soil visible outside of excavation and fencing.



Stained soil visible outside of excavation and fencing.





Stained soil visible outside of excavation and fencing.

