

Two open excavations with snow accumulation in close proximity to Weld County Road 46.  
Unmarked soil stockpiled on location.





Orange construction fencing is present but is beginning to fall in places.




Snow has accumulated within excavations.





Unmarked soil stockpiled on location.



No environmental impacts were visible in-situ in exposed areas of the excavation.





