


Three excavations remain open with orange construction fencing.




Three excavations remain open with orange construction fencing.





Orange construction fencing does not fully surround middle excavation. Snow has accumulated.



Two unmarked soil stockpiles on location; BMPs are adequate.






Snow has accumulated in excavation.




Orange construction fencing does not fully surround south excavation.






Bird netting is present. Snow has accumulated.




Apparent frozen groundwater observed within the southern excavation.






Wildlife tracks observed.



Wildlife tracks observed.





Orange construction fencing surrounds north excavation. Bird netting is present. Snow has accumulated.



Orange construction fencing surrounds north excavation. Bird netting is present. Snow has accumulated.

