

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100085**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS
,		inspections@civiresources.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488883	SPILL OR RELEASE	CL	12/17/2024		-	Maier 1	EI
488884	SPILL OR RELEASE	CL			-	Ursula-62N66W 28NENE	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill IDs: 488883 and 488884

Spill Names: Maier 1 and Ursula-62N66W 28NENE

Remediation Project #s: 37471 and 37481

Wellhead API and Facility ID: 05-123-09189 and 333219

Reported Dates of Discovery: 12/17/2024 and 12/18/2024

Date of Inspection: 01/15/2025

Spill is located within or adjacent to:

-Crop field

Current site status:

-Stockpiles associated with the release have been removed.

-Excavations have been backfilled.

-Riser observed missing OOSLAT.

-Trash observed on location.

See attached corrective actions. A Supplemental Form 27 is required.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	TRASH			
Comment:	Trash observed on location.			
Corrective Action:	Comply with Rule 606.			Date: 02/04/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type:	#			corrective date
Comment:	Riser observed missing OOSLAT.			
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.			Date: 01/30/2025
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 37471 was created for the plugging and abandonment of the Maier 1 wellhead and the removal of the associated flowline. Stockpiles associated with the release have been removed. No environmental impacts were visible. Quarterly reporting is required under Remediation Project No. 37471. Remediation Project No. 37481 was created for decommissioning of the Ursula-62N66W 28NENE facility. Excavations have been backfilled. No environmental impacts were visible. Quarterly reporting was required under Remediation Project No. 37481; the last Form 27 for this project was submitted 10/07/2024 (Document No. 403946342).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 37481.

Date: 02/11/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

	Piles				
Comment	Stockpiles associated with the release have been removed.				
Corrective Action					Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100086	ECMC Photo Log - Maier 1 and Ursula-62N66W 28NENE	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892872