

# Inspection Photos

01/22/2025

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334911

**Inspection Doc:** 718100217

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334911



**Photo 1:** Photos taken from the Location entrance on the southwest end of the working pad surface. Photos provide an overview of the Location from north and northeast.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334911



**Photo 2:** Photos examples showing the interim areas on the west and north ends of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334911



**Photo 3:** Photos taken from the southeastern areas of the Location. Photo shows areas recently disturbed during work associated with Remediation Project #34720. It is not apparent that revegetation activities have been performed within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources