

# Inspection Photos

01/22/2025

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334940

**Inspection Doc:** 718100219

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



**Photo 1:** Photos taken from the Location entrance on the northwest end of the working pad surface. Photos provide an overview of the Location from southwest to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



**Photo 2:** Photos examples showing the interim areas of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



**Photo 3:** Photos taken from the northern 400 bbl condensate tank. Condensate appears to have leaked from the top of the tank, spilling into the secondary containment. Spill does not appear to be active.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



**Photo 4:** Continued from photo 3. Photo shows tank where spill occurred.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



January 22, 2025



January 22, 2025

**Photo 5:** Photos 5-7 taken from the secondary containment measure at the 500 bbl condensate tank, on the north end of the Location. Photos show tears/holes within the liner of the containment BMP.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334940



January 22, 2025

**Photo 7:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources