


**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3390 Entrance to location**

**Photo # 3408 Location**

**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3391 Location**



**Photo # 3404 Location**

**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3407 Location**



**Photo # 3457 NE corner of location**



**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3460 NW corner of location**



**Photo # 3461 SW corner of location**

**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3462 SE corner of location**



**Photo # 3425 Staining**



Inspection/Audit Photos  
Location: QB ENERGY Mesa/F26-697  
Location ID: 448472  
Date: 01/27/2025



Photo # 3431 Staining



Photo # 3438 Staining



Inspection/Audit Photos  
Location: QB ENERGY Mesa/F26-697  
Location ID: 448472  
Date: 01/27/2025



Photo # 3442 Staining



Photo # 3445 Staining



**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3447 Staining**



**Photo # 3402 Staining around wellhead**



**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3418 Open ended load line**



**Photo # 3419 Open ended load line**

**Inspection/Audit Photos**  
**Location: QB ENERGY Mesa/F26-697**  
**Location ID: 448472**  
**Date: 01/27/2025**



**Photo # 3421 Open ended load line**