

Inspection Photos

January 24th, 2024

Operator: Abundance Energy - 10840

Location ID: 333779

Inspection Document #: 714001764

La Plata County, CO

Township: NWNE 27 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

1/24/25
69° E



Photo 1. View of the well pad from the access point facing center. Note: location/well signs not displaying current operator.

Inspection Photos
Location Name: Jacques 3, 7F
Location ID: 333779



Photo 2. Marked guyline anchor.

Inspection Photos
Location Name: Jacques 3, 7F
Location ID: 333779



Photo 3. Rill erosion forming on the northern and eastern edges of the active pad.

Inspection Photos
Location Name: Jacques 3, 7F
Location ID: 333779

1/24/25
202° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Eastern interim reclamation area composed of Western Wheatgrass, Sand Dropseed and Rubber Rabbitbrush.

API #: 067-06274, 08767

Inspection Photos
Location Name: Jacques 3, 7F
Location ID: 333779



Inspection Photos
Location Name: Jacques 3, 7F
Location ID: 333779

1/24/25
22° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Sand Dropseed, Juniper, Sagebrush and Rabbitbrush.

API #: 067-06274, 08767