

Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 3: Fencing in disrepair



Photo 4: Fencing in disrepair

Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 5: Location from entrance



Photo 6: Tank Battery Sign



Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 7: Holes/damage to earth berm



Photo 8: Holes/damage to earth berm

Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 8: Hole/damage to earth berm



Photo 9: Holes/damage to earth berm



Inspection Photos
Location Name: HSR-Moser 15-27
Location ID: 330725



Photo 10: hole/damage to earth berm