

Inspection Photos
Location Name: Sheldon R. Sickler 3
Location ID: 318317



Photo 1 Location



Photo 2 Wellhead.

Inspection Photos
Location Name: Sheldon R. Sickler 3
Location ID: 318317



Photo 3 Wellhead sign.

Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Sheldon R. Sickler 3
Location ID: 318317



Photo 5 Dead vegetation around the ROW & equipment.

Photo 6 Dead vegetation around the ROW & equipment.