

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 1/28/2025



Location Overview – Photo #06219



Location – Photo #06220

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 1/28/2025



Location – Photo #06221



Location – Photo #06225

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 1/28/2025



Location – Photo #06233




Location – Photo #06223

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 1/28/2025



Location – Photo #06222



Open-Ended Load Line – Photo #06241

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28SESW

Location ID: 335078

Date: 1/28/2025



Stained Soil – Photo #06226