

Inspection/Audit Photos


Location Name: QB Energy ASPEN RM 10-6C (F10E) Pad

Location ID: 324224



Jan 28, 2025 at 2:06:54 PM

Photo # 1963 From entrance to location



Jan 28, 2025 at 2:19:12 PM
CO

Photo # 1964 Location

Inspection/Audit Photos
Location Name: QB Energy ASPEN RM 10-6C (F10E) Pad
Location ID: 324224



Photo # 1965 Location



Photo # 1966 Location

Inspection/Audit Photos
Location Name: QB Energy ASPEN RM 10-6C (F10E) Pad
Location ID: 324224



Photo # 1967 Location



Photo # 1968 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos
Location Name: QB Energy ASPEN RM 10-6C (F10E) Pad
Location ID: 324224

Jan 28, 2025 at 2:12:45 PM

| CAERUS | | OIL AND GAS LLC | |
|--------------------------------------------------------------------------------------|-------------------|------------------|-------|
| TUBE SERIAL # 0140144 | | MVS# | |
| PAD | SECTION | TOWNSHIP | RANGE |
| FIDE | 10 | 74 | 92W |
| COUNTY | STATE | ELEV. | |
| Garfield | CO | 6047' | |
| METER # | METER NAME | | |
| 30007367 | Aspen RM 10-6C | | |
| MAKE | MODEL | SERIAL # | |
| Weatherford | CM-MVT | 12345678901234 | |
| DIFF. RANGE | STATIC RANGE | TEMP. RANGE | |
| 0-400" H ₂ O | 0-1500 PSIG | 0-150°F | |
| DIFF. CAL. RANGE | STATIC CAL. RANGE | TEMP. CAL. RANGE | |
| 0-400" H ₂ O | 0-750 PSIG | 0-150°F | |
| TAP LOCATION | RUN SIZE | BASE PRESS. | |
| <input checked="" type="checkbox"/> UP STREAM / <input type="checkbox"/> DOWN STREAM | 2.007 | 14.73 | |
| AT MO. PRESSURE | LATITUDE | LONGITUDE | |
| 11.70 | 39.462027 | -107.6520223 | |
| STRAIGHTNING VEIN LOCATION | | | |
| NO | | | |
| FLOW CONDITIONER MAKE | MODEL | LOCATION | |
| NO | | | |

Photo # 1969 Cal card

Jan 28, 2025 at 2:12:51 PM

| DATE | PLATE SIZE IN | PLATE SIZE OUT | PLATE INSP | CALIB | METER TUBE INSP | SAMPLE | BETA RATIO | SPECIFIC GRAVITY | BTU | CC2 | KG |
|---------|---------------|----------------|------------|-------|-----------------|---------|------------|------------------|---------|-------|------|
| 1/28/24 | 250 | 250 | Q11 | Q11 | 5/15/24 | 4-28-24 | 36 | 6745 | 1170.8 | 0.072 | 0.18 |
| 1/22/24 | 250 | 250 | SK | SK | - | 4-21-24 | 36 | 6740 | 1174.06 | 0.073 | 0.15 |
| 1/10/23 | 250 | 250 | SK | SK | - | 4/10/24 | 36 | 6560 | 1170.8 | 0.072 | 0.18 |

Photo # 1970 Meter not calibrated annually/not in compliance with CECMC rules

Inspection/Audit Photos
Location Name: QB Energy ASPEN RM 10-6C (F10E) Pad
Location ID: 324224



Photo # 1971 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 1972 PRV vent line does not comply with CECMC pressure safety device rules