

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 1136 From entrance to location



Photo # 1137 From entrance to location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 1138 Location



Photo # 1139 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 1140 Location



Photo # 1141 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



Photo # 1142 Location



Photo # 1143 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038



**Photo # 1144 Cellar not properly covered/wildlife & personnel hazard**



**Photo # 1145 Cellar not properly covered/wildlife hazard**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH B Pad

Location #: 336038




Photo # 1146 Tank label weathered & damaged

