

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 1/30/2025



Location Overview – Photo #06343



Location – Photo #06344

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 1/30/2025



Location – Photo #06347



Location – Photo #06350

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 1/30/2025



Location – Photo #06351




Fallen Wellhead Fencing – Photo #06345

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 1/30/2025



Illegible Wellhead Sign – Photo #06346



Stored Supplies/Wildlife Entry Hazard – Photo #06353

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 1/30/2025



**Stored Supplies/Wildlife Entry Hazard – Photo #06354**