

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign – Faded Info no longer visible

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 3 – Holes in Berm



Photo 4 – Tank Battery

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 5 – Holes in Berm



Photo 6 – Holes in Berm

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 7 – Tank Battery



Photo 8 – Heater Treater, ECD, Flare and Propane Tank

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 9 – Pumping Unit



Photo 10 – Wellhead

Inspection Photos
Location Name: Birds of Prey 36-10-61
Location ID: 420207



Photo 11 – Pumping Unit