

Inspection Photos

Feburary 3rd, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 306776

Inspection Document #: 714001771

La Plata County, CO

Township: SENW 8 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Koshak B-4A
Location ID: 306776



Photo 1. View of the well pad from the access point facing center.

Inspection Photos
Location Name: Koshak B-4A
Location ID: 306776



Photo: Oily substance at pump jack has been removed.



Inspection Photos
Location Name: Koshak B-4A
Location ID: 306776



Photo 3. Small pile of trash observed on the northern fence line.



Inspection Photos
Location Name: Koshak B-4A
Location ID: 306776

2/3/25
351° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Eastern interim reclamation area composed of Sand Dropseed, Prairie Sunflower and Rabbitbrush.

API #: 067-08736

Inspection Photos
Location Name: Koshak B-4A
Location ID: 306776

2/3/25
178° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Rabbitbrush, Sagebrush, Yucca, Grama and Sand Dropseed.

API #: 067-08736