

## Inspection/Audit Photos

Location Name: QB Energy KRK 7-16 (P7E) Pad

Location #: 334854



Photo # 3636 From entrance to location




Photo # 3637 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-16 (P7E) Pad**  
**Location #: 334854**



Feb 5, 2025 at 12:20:13 PM  
CO

**Photo # 3638 Location**



Feb 5, 2025 at 12:25:51 PM  
CO

**Photo # 3639 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-16 (P7E) Pad**  
**Location #: 334854**



**Photo # 3640 Location**



**Photo # 3641 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-16 (P7E) Pad**  
**Location #: 334854**



**Photo # 3642 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**



**Photo # 3643 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**