

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530




Photo # 2433 From entrance to location

Photo # 2434 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2435 Location



Photo # 2436 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeffli RWF 32-36 Pad

Location ID: 335530



Photo # 2437 Location



Photo # 2438 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2439 Location



Photo # 2440 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 32-36 Pad

Location ID: 335530



Photo # 2441 Location



Photo # 2442 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2443 Location



Photo # 2444 Debris

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2352 From inspection 708904676 conducted on 09/26/2024 Stored trailer on location



Photo # 2445 Stored trailer on location (Stored ATV added to trailer since last inspection)

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



**Photo # 2353 From inspection 708904676 conducted on 09/26/2024 Stored generator on location**

**Photo # 2446 Stored generator on location**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Sep 26, 2024 at 1:09:59 PM  
CO



Jan 29, 2025 at 2:14:55 PM  
CO

Photo # 2354 From inspection 708904676 conducted on 09/26/2024 Stored shipping container, snowmobiles & misc on location

Photo # 2447 Stored shipping container, snowmobiles & misc on location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



**Photo # 2355 From inspection 708904676 conducted on 09/26/2024 Stored logs on location**

**Photo # 2448 Stored logs on location**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeffli RWF 32-36 Pad

Location ID: 335530



Photo # 2356 From inspection 708904676 conducted on 09/26/2024 Stored misc & Improperly stored fuel container on location



Photo # 2449 Stored misc & Improperly stored fuel container on location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2450 Additional stored equipment in the interim area



Photo # 2451 Additional stored equipment & trailer on location