

Inspection Photos

February 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326640

Inspection Document #: 714001776

La Plata County, CO

Township: SESE 20 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Arthur Mason B2
Location ID: 326640



Photo 1. View of the well pad from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08506

Inspection Photos
Location Name: Arthur Mason B2
Location ID: 326640



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo: Stained soils at pump jack muffler/hose.

API #: 067-08506

Inspection Photos
Location Name: Arthur Mason B2
Location ID: 326640



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Gravel/woody debris have been removed from the active pad.

API #: 067-08506

Inspection Photos
Location Name: Arthur Mason B2
Location ID: 326640



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Western interim reclamation area composed of Intermediate Wheatgrass and Sand Dropseed.

API #: 067-08506

Inspection Photos
Location Name: Arthur Mason B2
Location ID: 326640



Photo 5. Irrigated grass field reference area.