

Inspection Photos

February 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326547

Inspection Document #: 714001778

La Plata County, CO

Township: SWNE 17 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: James Cole A2
Location ID: 326547



Photo 1. View of the well pad from the access point facing center.

Inspection Photos
Location Name: James Cole A2
Location ID: 326547



Photo: Produced water tank label has deteriorated and is no longer displaying capacity.

Inspection Photos
Location Name: James Cole A2
Location ID: 326547

2/3/25
133° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Gravel pile removed from active pad surface.

API #: 067-08285

Inspection Photos
Location Name: James Cole A2
Location ID: 326547

2/3/25
36° NE



Photo 4. Irrigated grass field reference area.