

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 2/5/2025



Location Overview – Photo #06436



Location – Photo #06437

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 2/5/2025



Location – Photo #06438



Location – Photo #06440

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 2/5/2025



Location – Photo #06439



Staining in Tank Containment – Photo #06441

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 2/5/2025



Staining in Tank Containment – Photo #06446



Leak at Valve Plug – Photo #06445

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 2/5/2025



Wildlife Entry Hazard – Photo #06447



Wildlife Entry Hazard – Photo #06449